

UNIT ADDRESS 405 Camp # _____ REPORT # _____

EXTERIOR LOCATIONS	SUBSTRATE						PAINT CONDITION			ALC	SEL	CLC	(NOTES)
SIDING <i>Viny /</i>	B	C			W	M		I	D	FF			
EXTERIOR TRIM <i>Viny /</i>	B	C			W	M	T	I	D	FF			
SOFFIT					W	M		I	D	FF			
FACIA					W	M		I	D	FF			
WINDOW EXTERIOR SASH					W	M		I	D	FF			
WINDOW TRIM					W	M		I	D	FF			
WINDOW PRIMARY SASH					W	M		I	D	FF		0.1	
WINDOW SILL					W	M		I	D	FF			
PORCH COLUMN		C			W	M		I	D	FF			
PORCH CEILING					W	M		I	D	FF			
PORCH FLOOR		C			W	M		I	D	FF			
STAIR STEPS		C			W	M		I	D	FF			
STAIR STRINGER					W			I	D	FF			
DOOR					W	M		I	D	FF		0.1	
DOOR TRIM					W	M		I	D	FF		0.1	
DOOR JAMB					W	M		I	D	FF		19.4	
SKIRTING	B	C	G	P	W	M	T	I	D	FF			
THRESHOLD	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			

ROOM NAME Bedroom 3

_____ REPORT # _____

COMPONENT	SUBSTRATE				PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD			Vinyl	W	M	I	D	FF			
CEILING <u>Tile</u>			G	P	W	M	I	D	FF		
DOOR				W	M	I	D	FF			
DOOR TRIM				W	M	I	D	FF			
SHELF				W	M	I	D	FF			
SHELF SUPPORT				W	M	I	D	FF			
WALL	B	C	G	P	W	M	T	I	D	FF	
WINDOW SASH				W	M	I	D	FF			
WINDOW TRIM				W	M	I	D	FF			
WINDOW SILL				W	M	I	D	FF			
FLOOR	CP		Vinyl	W		I	D	FF			
	B	C	G	P	W	M	T	I	D	FF	
	B	C	G	P	W	M	T	I	D	FF	
	B	C	G	P	W	M	T	I	D	FF	

ROOM NAME Hall to Stairway

_____ REPORT # _____


COMPONENT	SUBSTRATE				PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD			Vinyl	W	M	I	D	FF			
CEILING <u>Tile</u>			G	P	W	M	I	D	FF		
DOOR				W	M	I	D	FF			
DOOR TRIM				W	M	I	D	FF			
SHELF				W	M	I	D	FF			
SHELF SUPPORT				W	M	I	D	FF			
WALL	B	C	G	P	W	M	T	I	D	FF	
WINDOW SASH				W	M	I	D	FF			
WINDOW TRIM				W	M	I	D	FF			
WINDOW SILL				W	M	I	D	FF			
FLOOR	CP		Vinyl	W		I	D	FF			
	B	C	G	P	W	M	T	I	D	FF	
	B	C	G	P	W	M	T	I	D	FF	
	B	C	G	P	W	M	T	I	D	FF	

ROOM NAME Basement + Back Hall

_____ REPORT # _____

COMPONENT	SUBSTRATE				PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD			Vinyl	W	M	I	D	FF			
CEILING			G	P	W	M	I	D	FF		0.0
DOOR				W	M	I	D	FF			2.5
DOOR TRIM				W	M	I	D	FF			3.8
SHELF				W	M	I	D	FF			
SHELF SUPPORT				W	M	I	D	FF			
WALL	B	C	G	P	W	M	T	I	D	FF	0.0
WINDOW SASH				W	M	I	D	FF			
WINDOW TRIM				W	M	I	D	FF			
WINDOW SILL				W	M	I	D	FF			
FLOOR	CP		Vinyl	W		I	D	FF			
<u>Stair</u>	B	C	G	P	W	M	T	I	D	FF	4.9
<u>Stairway</u>	B	C	G	P	W	M	T	I	D	FF	4.4
<u>Wainscott</u>	B	C	G	P	W	M	T	I	D	FF	4.6

187



ROOM NAME Living Room

REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M		I	D	(FF)				
CEILING			G	(P)	W	M		(D)	D	FF			0.0	
DOOR					(W)	M		I	D	(FF)				
DOOR TRIM					(W)	M		I	D	(FF)				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	(P)	W	M	T	(D)	D	FF			0.1	
WINDOW SASH					(W)	M		I	D	(FF)				
WINDOW TRIM					(W)	M		I	D	(FF)				
WINDOW SILL					(W)	M		I	D	(FF)				
FLOOR	(CP)			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Dining Room

REPORT # _____


COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M		I	D	(FF)				
CEILING			G	(P)	W	M		(D)	D	FF			0.3	
DOOR					W	M		I	D	FF				
DOOR TRIM					(W)	M		I	D	(FF)				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	(P)	W	M	T	(D)	D	FF			0.3	
WINDOW SASH					(W)	M		I	D	(FF)				
WINDOW TRIM					(W)	M		I	D	(FF)				
WINDOW SILL					(W)	M		I	D	(FF)				
FLOOR	CP			(Vinyl)	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Kitchen

REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M		I	D	FF				
CEILING			G	(P)	W	M		(D)	D	FF			0.1	
DOOR					(W)	M		(D)	D	FF			0.3	
DOOR TRIM					(W)	M		(D)	D	FF			0.0	
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	(P)	W	M	T	(D)	D	FF			0.1	
WINDOW SASH					W	(M)		I	D	FF				
WINDOW TRIM					(W)	M		(D)	D	FF			0.0	
WINDOW SILL					(W)	M		(D)	D	FF			12.4	
FLOOR	CP			(Vinyl)	W			I	D	FF				
<u>Cupboard</u>	B	C	G	P	(W)	M	T	I	D	(FF)			0.0	
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

1st



ROOM NAME Bedroom 1

REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M		I	D	FF				
CEILING			G	P	W	M		⓪	D	FF			0.0	
DOOR					W	M		I	D	FF				
DOOR TRIM					W	M		I	D	FF				
SHELF					W	M		⓪	D	FF			0.1	
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	W	M	T	⓪	D	FF			0.0	
WINDOW SASH					W	M		I	D	FF				
WINDOW TRIM					W	M		I	D	FF				
WINDOW SILL					W	M		I	D	FF				
FLOOR	CP			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bedroom 2

REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M		I	D	FF				
CEILING			G	P	W	M		⓪	D	FF			0.0	
DOOR					W	M		I	D	FF				
DOOR TRIM					W	M		I	D	FF				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	W	M	T	⓪	D	FF			0.3	
WINDOW SASH					W	M		I	D	FF				
WINDOW TRIM					W	M		I	D	FF				
WINDOW SILL					W	M		I	D	FF				
FLOOR	CP			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bath

REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M		I	D	FF				
CEILING			G	P	W	M		⓪	D	FF			0.0	
DOOR					W	M		⓪	D	FF			0.1	
DOOR TRIM					W	M		⓪	D	FF			0.2	
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	W	M	T	⓪	D	FF			0.0	
WINDOW SASH					W	M		I	D	FF				
WINDOW TRIM					W	M		I	D	FF				
WINDOW SILL					W	M		I	D	FF				
FLOOR	CP			Vinyl	W			I	D	FF				
Wainscot	B	C	G	P	W	M	T	⓪	D	FF			0.3	
Medicine Chest	B	C	G	P	W	M	T	⓪	D	FF			0.1	
	B	C	G	P	W	M	T	I	D	FF				