

ENVIRONMENTAL CONTROL TECHNOLOGIES

LBP XK-3 SAMPLE SHEET

Date/Time: March 11, 1993 Apartment # 207 Center St. Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
<u>Stairway/D</u>	.1	.1	.1	.10								Negative
EDC	0	.1	.2	.10								Negative
DJ	.2	.1	0	.10								Negative
Window Pane	2.9	3.1	3.4	3.13								Abate
Siding Brown	10.0	10.0	10.0	10.0								Abate
Ceiling Brown	9.1	9.0	9.2	9.10								Abate
<u>Exterior</u>												
Siding/Gold	4.1	4.2	4.4	4.23								Abate
Porch Posts	3.7	3.4	3.6	3.56								Abate
Porch Ceiling	0	.1	0	.03								Negative
Porch Beam	10.0	10.0	10.0	10.0								Abate
Soffitt	3.1	3.5	3.9	3.5								Abate
Porch Rail	4.2	4.7	3.9	4.26								Abate

Concrete/Gray 1.3 1.2 1.3 1.26 .9 .9 .9 .90 .36 Negative

