

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 10, 1993 Apartment # 1019 Fourth St. Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
LR/W	.5	.6	.3	.46								Negative
LR/CE	0	.4	.2	.20								Negative
LR/IDC	0	0	0	0								Negative
LR/DJ	8.9	8.5	8.6	8.6								Abate
LR/BB	0	0	0	0								Negative
LR/WS	0	0	0	0								Negative
LR/WC	0	0	0	0								Negative
LR/Window Pane	1.2	.7	1.4	1.1	.3	.8	.5	.53	.57	1019-01	8697 ppm	ABATE
LR/Window Jamb	3.9	3.5	3.7	3.7								Abate
Bedroom #1/W	4.6	4.9	4.5	4.6								Abate
C	4.8	5.1	4.9	4.9								Abate
EDC	0	.1	0	.03								Negative
DJ	.7	.5	.3	.5	.4	.4	.4	.40	.10			Negative

Paneling on Walls/Exterior of House Aluminum Siding

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 10, 1993 Apartment # 1019 Fourth St. Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Door	.2	.2	.1	.16								Negative
<u>Dining Room</u>												
Wall	.2	0	.1	.1								Negative
Ceiling *	0	.1	.1	.06								Negative
BB	0	0	.1	.03								Negative
WS	.2	0	.1	.1								Negative
WC	0	0	0	0								Negative
WP	.2	.2	.2	.2								Negative
WJ	2.9	4.7	3.6	3.7								Abate
<u>Bedroom #2</u>												
W	3.9	3.5	3.6	3.6								Abate
C	0	.1	.2	.1								Negative
EDC	0	.1	.2	.1								Negative

*12x12 Ceiling Tile directly on ceiling above drop ceiling.

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 10, 1993 Apartment # 1019 Fourth St. Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg/Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Door	0	0	.1	.03								Negative
DJ	0	0	.2	.06								Negative
<u>Restroom *</u>												
Door	0	0	0	0								Negative
EDC	0	0	.1	.03								Negative
DJ	0	0	.2	.06								Negative
IDC	0	0	0	0								Negative
BB	0	.1	0	.03								Negative
Wood Paneling	0	0	0	0								Negative
Cabinet Door	0	0	0	0								Negative
Cabinet Casing	0	0	.1	.03								Negative
Cabinet Shelf	0	0	0	0								Negative
Window Sill	0	0	0	0								Negative

* Walls and Ceiling covered with paneling

