ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: February 17, 1993 Apartment # 2611 Harbor Dr. Project: Area 7 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
LR/DJ	0	0	0	0								Negative
LR/DC Metal	.8	.6	.6	.66	.5	.4	.4	.43	.23			Negative
LR/W	0	0	.1	.03								Negative
LR/C	0	0	0	0								Negative
LR/C Wood Shelf	.3	.3	.2	.26								Negative
K/W	0	0	.1	.03								Negative
K/D Metal	.7	.6	.6	.63	.5	.5	.5	.50	.13			Negative
K/CW #1	0	0	0	0								Negative
K/C Wood Shelf	0	.1	.1	.06								Negative
K/CE #2	0	.1	.1	.06								Negative
K/C Wood Shelf	0	.1	0	.03								Negative
HC	0	0	0	0								Negative
RR/W	0	0	0	0								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: February 17, 1993 Apartment # 2611 Harbor Dr. Project: Area 7 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
BR 1/W	0	0	0	0								Negative
Ceiling	0	.1	.1	.06								Negative
BR 1/CW	0	.1	.1	.06								Negative
BR 1/Shelf	0	.1	0	.03								Negative
BR 1/Bracket	0	0	.1	.03								Negative
BR 2/W	0	.1	0	.03								Negative
Ceiling	0	.1	.1	.06								Negative
BR 2/CW	0	.1	.1	.06								Negative
BR 2/Shelf	0	0	0	0								Negative
BR 2/Bracket	0	0	0	0								Negative
Electrical Panel	1.0	.9	.9	.93	1.0	.8	.8	.86	.07			Negative