



















ENVIRONMENTAL CONTROL TECHNOLOGIES  
LBP XK-3 SAMPLE SHEET

Date/Time: March 12, 1993 Apartment # 905 Hayes Project: Area 8 Site: Erie Metro. H.A.

| Sample Number         | Reading (mg/cm <sup>2</sup> ) |     |     |     | S.E.L. (mg/cm <sup>2</sup> ) |   |   |     | C.L.C. (mg/cm <sup>2</sup> ) | Conformation Test |        | Result Neg./Abate |
|-----------------------|-------------------------------|-----|-----|-----|------------------------------|---|---|-----|------------------------------|-------------------|--------|-------------------|
|                       | 1                             | 2   | 3   | Avg | 1                            | 2 | 3 | Avg |                              | No.               | Result |                   |
| Door                  | 8.5                           | 8.1 | 8.0 | 8.2 |                              |   |   |     |                              |                   |        | Abate             |
| DJ                    | 0                             | .1  | .1  | .06 |                              |   |   |     |                              |                   |        | Negative          |
| IDC                   | 0                             | 0   | 0   | 0   |                              |   |   |     |                              |                   |        | Negative          |
| EDC                   | 0                             | .1  | .2  | .10 |                              |   |   |     |                              |                   |        | Negative          |
| <u>Bdrm #2 Closet</u> |                               |     |     |     |                              |   |   |     |                              |                   |        |                   |
| Wall                  | .1                            | .1  | .1  | .10 |                              |   |   |     |                              |                   |        | Negative          |
| Ceiling               | 0                             | 0   | 0   | 0   |                              |   |   |     |                              |                   |        | Negative          |
| Floor                 | .4                            | .4  | .4  | .40 |                              |   |   |     |                              |                   |        | Negative          |
| Shelf                 | .1                            | .1  | .1  | .10 |                              |   |   |     |                              |                   |        | Negative          |
| SB                    | 0                             | .1  | .1  | .06 |                              |   |   |     |                              |                   |        | Negative          |
| Door                  | .3                            | .3  | .3  | .30 |                              |   |   |     |                              |                   |        | Negative          |
| DJ                    | 0                             | .1  | .2  | .10 |                              |   |   |     |                              |                   |        | Negative          |
| EDC                   | 0                             | 0   | 0   | 0   |                              |   |   |     |                              |                   |        | Negative          |

IDC .1 .1 .1 .10

Negative







ENVIRONMENTAL CONTROL TECHNOLOGIES  
LBP XK-3 SAMPLE SHEET

Date/Time: March 12, 1993 Apartment # 905 Hayes Project: Area 8 Site: Erie Metro. H.A.

| Sample Number     | Reading (mg/cm <sup>2</sup> ) |      |      |      | S.E.L. (mg/cm <sup>2</sup> ) |    |    |     | C.L.C. (mg/cm <sup>2</sup> ) | Conformation Test |        | Result Neg./Abate |
|-------------------|-------------------------------|------|------|------|------------------------------|----|----|-----|------------------------------|-------------------|--------|-------------------|
|                   | 1                             | 2    | 3    | Avg  | 1                            | 2  | 3  | Avg |                              | No.               | Result |                   |
| BB                | .1                            | .1   | .1   | .10  |                              |    |    |     |                              |                   |        | Negative          |
| Door              | 0                             | 0    | 0    | 0    |                              |    |    |     |                              |                   |        | Negative          |
| Shair Header      | .1                            | .1   | .1   | .10  |                              |    |    |     |                              |                   |        | Negative          |
| Stair Stringer    | 9.0                           | 9.0  | 9.0  | 9.0  |                              |    |    |     |                              |                   |        | Abate             |
| Baseboard         | .2                            | .2   | .2   | .20  |                              |    |    |     |                              |                   |        | Negative          |
| Hand Rail         | .2                            | .3   | .2   | .23  |                              |    |    |     |                              |                   |        | Negative          |
| Pipe              | 1.4                           | 1.2  | 1.1  | 1.23 | .9                           | .9 | .9 | .90 | .33                          |                   |        | Negative          |
| Door              | .3                            | .2   | .3   | .26  |                              |    |    |     |                              |                   |        | Negative          |
| EDC               | .1                            | .1   | .1   | .10  |                              |    |    |     |                              |                   |        | Negative          |
| IDC               | 10.0                          | 10.0 | 10.0 | 10.0 |                              |    |    |     |                              |                   |        | Abate             |
| DJ                | 3.0                           | 3.0  | 3.0  | 3.0  |                              |    |    |     |                              |                   |        | Abate             |
| <u>Bedroom #5</u> |                               |      |      |      |                              |    |    |     |                              |                   |        |                   |
| Wall              | 0                             | 0    | 0    | 0    |                              |    |    |     |                              |                   |        | Negative          |

Ceiling .5 .5 .4 .46

Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES  
LBP XK-3 SAMPLE SHEET

Date/Time: March 12, 1993 Apartment # 905 Hayes Project: Area 8 Site: Erie Metro. H.A.

| Sample Number         | Reading (mg/cm <sup>2</sup> ) |    |    |     | S.E.L. (mg/cm <sup>2</sup> ) |   |   |     | C.L.C. (mg/cm <sup>2</sup> ) | Conformation Test |        | Result Neg./Abate |
|-----------------------|-------------------------------|----|----|-----|------------------------------|---|---|-----|------------------------------|-------------------|--------|-------------------|
|                       | 1                             | 2  | 3  | Avg | 1                            | 2 | 3 | Avg |                              | No.               | Result |                   |
| BB                    | 0                             | .1 | .1 | .06 |                              |   |   |     |                              |                   |        | Negative          |
| Door                  | 0                             | 0  | 0  | 0   |                              |   |   |     |                              |                   |        | Negative          |
| DJ                    | .2                            | .2 | .2 | .20 |                              |   |   |     |                              |                   |        | Negative          |
| IDC                   | 0                             | 0  | 0  | 0   |                              |   |   |     |                              |                   |        | Negative          |
| EDC                   | 0                             | 0  | 0  | 0   |                              |   |   |     |                              |                   |        | Negative          |
| WC                    | 0                             | .1 | .1 | .06 |                              |   |   |     |                              |                   |        | Negative          |
| WS                    | 0                             | 0  | 0  | 0   |                              |   |   |     |                              |                   |        | Negative          |
| <u>Bdrm #5 Closet</u> |                               |    |    |     |                              |   |   |     |                              |                   |        |                   |
| Wall                  | 0                             | .1 | .1 | .06 |                              |   |   |     |                              |                   |        | Negative          |
| Ceiling               | .1                            | .1 | .1 | .10 |                              |   |   |     |                              |                   |        | Negative          |
| BB                    | 0                             | 0  | 0  | 0   |                              |   |   |     |                              |                   |        | Negative          |
| Shelf                 | 0                             | .1 | .2 | .10 |                              |   |   |     |                              |                   |        | Negative          |
| SB                    | 0                             | 0  | 0  | 0   |                              |   |   |     |                              |                   |        | Negative          |

Floor .4 .4 .3 .36 Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES  
LBP XK-3 SAMPLE SHEET

Date/Time: March 12, 1993 Apartment # 905 Hayes Project: Area 8 Site: Erie Metro. H.A.

| Sample Number   | Reading (mg/cm <sup>2</sup> ) |     |     |      | S.E.L. (mg/cm <sup>2</sup> ) |    |    |     | C.L.C. (mg/cm <sup>2</sup> ) | Conformation Test |        | Result Neg./Abate |
|-----------------|-------------------------------|-----|-----|------|------------------------------|----|----|-----|------------------------------|-------------------|--------|-------------------|
|                 | 1                             | 2   | 3   | Avg  | 1                            | 2  | 3  | Avg |                              | No.               | Result |                   |
| Door            | .1                            | .1  | .1  | .10  |                              |    |    |     |                              |                   |        | Negative          |
| IDC             | 0                             | 0   | 0   | 0    |                              |    |    |     |                              |                   |        | Negative          |
| DJ              | .1                            | .1  | .1  | .10  |                              |    |    |     |                              |                   |        | Negative          |
| EDC             | 0                             | .1  | .1  | .06  |                              |    |    |     |                              |                   |        | Negative          |
| <u>Basement</u> |                               |     |     |      |                              |    |    |     |                              |                   |        |                   |
| Stairs          | 0                             | .1  | .1  | .06  |                              |    |    |     |                              |                   |        | Negative          |
| Wall            | 2.9                           | 3.4 | 3.0 | 3.1  |                              |    |    |     |                              |                   |        | Abate             |
| Ceiling         | 2.2                           | 3.7 | 3.5 | 3.1  |                              |    |    |     |                              |                   |        | Abate             |
| Door            | .7                            | .7  | .7  | .70  | .6                           | .6 | .6 | .60 | .10                          |                   |        | Negative          |
| DJ              | 7.0                           | 6.8 | 6.7 | 6.83 |                              |    |    |     |                              |                   |        | Abate             |
| IDC             | 8.3                           | 8.0 | 8.1 | 8.13 |                              |    |    |     |                              |                   |        | Abate             |
| EDC             | 0                             | 0   | .1  | .03  |                              |    |    |     |                              |                   |        | Negative          |
| Shelf           | 3.7                           | 3.5 | 3.6 | 3.6  |                              |    |    |     |                              |                   |        | Abate             |

Cabinet            10.0   10.0   10.0   10.0

Abate

ENVIRONMENTAL CONTROL TECHNOLOGIES  
LBP XK-3 SAMPLE SHEET

Date/Time: March 12, 1993 Apartment # 905 Hayes Project: Area 8 Site: Erie Metro. H.A.

| Sample Number     | Reading (mg/cm <sup>2</sup> ) |      |      |      | S.E.L. (mg/cm <sup>2</sup> ) |    |    |     | C.L.C. (mg/cm <sup>2</sup> ) | Conformation Test |        | Result Neg./Abate |
|-------------------|-------------------------------|------|------|------|------------------------------|----|----|-----|------------------------------|-------------------|--------|-------------------|
|                   | 1                             | 2    | 3    | Avg  | 1                            | 2  | 3  | Avg |                              | No.               | Result |                   |
| Stair Header      | 4.9                           | 4.0  | 4.5  | 4.46 |                              |    |    |     |                              |                   |        | Abate             |
| Stair Support     | 5.2                           | 5.0  | 4.8  | 5.0  |                              |    |    |     |                              |                   |        | Abate             |
| Window Pane       | 3.6                           | 3.5  | 3.2  | 3.43 |                              |    |    |     |                              |                   |        | Abate             |
| <u>Exterior</u>   |                               |      |      |      |                              |    |    |     |                              |                   |        |                   |
| Siding            | 10.0                          | 10.0 | 10.0 | 10.0 |                              |    |    |     |                              |                   |        | Abate             |
| Windows           | Covered with aluminum         |      |      |      |                              |    |    |     |                              |                   |        |                   |
| Porch Header      | 10.0                          | 10.0 | 10.0 | 10.0 |                              |    |    |     |                              |                   |        | Abate             |
| Handrail          | 1.1                           | 1.1  | 1.1  | 1.1  | .7                           | .7 | .7 | .70 | .40                          |                   |        | Negative          |
| Ceiling           | .1                            | .1   | .1   | .10  |                              |    |    |     |                              |                   |        | Negative          |
| Soffitt           | 10.0                          | 10.0 | 10.0 | 10.0 |                              |    |    |     |                              |                   |        | Abate             |
| <u>Rear Porch</u> |                               |      |      |      |                              |    |    |     |                              |                   |        |                   |
| Post              | 10.0                          | 10.0 | 10.0 | 10.0 |                              |    |    |     |                              |                   |        | Abate             |
| Header            | 10.0                          | 10.0 | 10.0 | 10.0 |                              |    |    |     |                              |                   |        | Abate             |

Ceiling            10.0   10.0   10.0   10.0

Abate



