

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 10, 1993 Apartment # 1617 Larchmont Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
<u>Utility Rm./Wall</u>	0	.1	0	.03								Negative
Ceiling	.1	0	.1	.06								Negative
BB	0	.1	0	.03								Negative
IDC	0	0	0	0								Negative
DJ	0	0	0	0								Negative
Metal Door	.5	.5	.4	.46								Negative
EP	.8	.6	.7	.70	.5	.4	.4	.43				Negative
<u>Bedroom #1</u>												
CE	0	0	0	0								Negative
IDC	0	0	0	0								Negative
EDC	0	0	.1	.03								Negative
DJ	0	.1	0	.03								Negative
BR #1 C/Wall	0	0	0	0								Negative

BR #1 Walls covered with paneling

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 10, 1993 Apartment # 1617 Larchmont Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Attic Casing	0	0	0	0								Negative
Fence	.1	0	0	.03								Negative
Fence Post	.1	0	0	.03								Negative