

ENVIRONMENTAL CONTROL TECHNOLOGIES

LBP XK-3 SAMPLE SHEET

Date/Time: February 16, 1993 Apartment # 424 Meigs Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Ceiling Tile Frame	.2	.2	.1	.16								Negative
Window Casing	0	0	.2	.06								Negative
BB	0	.1	0	.03								Negative
Bookshelf Cas.	.3	.3	.1	.23								Negative
Support Bm./Met.	1.6	1.3	1.5	1.46								Abate
Fl/Concrete	1.1	.9	1.2	1.06	.6	.6	.6	.60	.46			Negative
White Con. Wall	.2	.3	.2	.23								Negative
White Wd. Wall	5.5	5.3	5.7	5.5								Abate
White W. Cas.	5.6	5.8	6.0	5.8								Abate
Stair Post	0	0	.1	.03								Negative
Stair Rail	0	.1	.2	.1								Negative
Stair Stringer	0	.2	.1	.1								Negative
Window Cas.	1.6	1.7	1.9	1.73								Abate

Stair covered with carpet.

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 9, 1993 Apartment # 424 Meigs Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
<u>Porch</u>												
Posts	2.7	3.4	3.9	3.33								Abate
Metal Rails	.4	.4	.4	.40								Negative
Porch/Conc.	.7	.7	.6	.66	.6	.5	.5	.53	.13			Negative
Black Door	5.6	5.9	5.6	5.7								Abate
Wind./Basement	.3	.3	.3	.30								Negative
Rear Porch Posts	10.0	10.0	10.0	10.0								Abate
<u>Garage</u>												
Door	0	0	0	0								Negative
DJ	10.0	10.0	10.0	10.0								Abate

Aluminum Siding