

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March 10, 1993 Apartment # 2717 W. Monroe Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
<u>Exterior</u>												
Handrails/Metal	1.1	1.0	1.0	1.03	.7	.7	.8	.73	.30			Negative
Porch Header	10.0	10.0	10.0	10.0								Abate
Porch Ceiling	6.1	5.9	5.7	5.9								Abate
Soffitt	10.0	10.0	10.0	10.0								Abate
Gutter	1.0	.9	.9	.93	.7	.7	.7	.70	.23			Negative
Basement/Win.	6.6	6.1	5.9	6.2								Abate
Fascia	10.0	10.0	10.0	10.0								Abate

All Window

