

W. O., LTD.

(A DIVISION OF SCHAUER & ASSOCIATES, INC.)
6960 S. 13th Street, P. O. Box 285
Oak Creek, WI. 53154-0285
(414)768-9588, (800)628-2590, Fax (414)764-2088

Report No. 13

ON SITE LEAD PAINT X-RAY FLUORESCENCE EVALUATION RECORD

AGENCY Eric Metropolitan Housing Authority
STREET 322 Warren Street UNIT/ADDRESS 1933 Second St.
CITY Sandusky, Ohio UNIT/LOCATION _____
DATE 10-26-93

Substrate:

- B - Brick
- C - Concrete
- G - Gypsum
- P - Plaster
- Ⓜ - Wood
- Ⓜ - Metal
- T - Tile
- CP - Carpet

Paint Condition:

- Ⓟ intact
- Ⓧ - defective (peeling, cracked, loose)
- FF - factory finish

Comments:

This testing was accomplished utilizing:

A Warrington Microlead I, Revision 4, X-Ray Fluoroscope
 A Scitec Map 3 Spectrum Analyzer, X-Ray Fluoroscope

SIGNATURES


[Signature]

Technician/Inspector

Agency Representative

No indication of Lead Based Paint in this unit.
 Paint samples taken for analysis _____ Lead indicated

1933 Second St.



UNIT ADDRESS 1933 Second St. # _____ REPORT # _____

EXTERIOR LOCATIONS	SUBSTRATE						PAINT CONDITION			ALC	SEL	CLC	(NOTES)
SIDING <i>Vinyl</i>	B	C			W	M		I	D	FF			
EXTERIOR TRIM <i>Vinyl</i>	B	C			W	M	T	I	D	FF			
SOFFIT					W	M		I	D	FF			
FACIA					W	M		I	D	FF			
WINDOW EXTERIOR SASH					W	M		I	D	FF			
WINDOW TRIM					W	M		I	D	FF			
WINDOW PRIMARY SASH					W	M		I	D	FF			
WINDOW SILL					W	M		I	D	FF			
PORCH COLUMN		C			W	M		I	D	FF			
PORCH CEILING					W	M		I	D	FF			
PORCH FLOOR		C			W	M		I	D	FF			
STAIR STEPS		C			W	M		I	D	FF			
STAIR STRINGER					W			I	D	FF			
DOOR					W	M		I	D	FF			0.0
DOOR TRIM					W	M		I	D	FF			
DOOR JAMB					W	M		I	D	FF			0.2
SKIRTING	B	C	G	P	W	M	T	I	D	FF			
THRESHOLD	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			

ROOM NAME Living Room

_____ REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
	B	C	G	P	W	M	T	I	D	FF				
BASEBOARD					Vinyl	(W)	M		(I)	D	FF			0.1
CEILING			(G)	P	W	M			(I)	D	FF			0.0
DOOR					(W)	M			(I)	D	FF			
DOOR TRIM					(W)	M			(I)	D	FF			0.1
SHELF					W	M			I	D	FF			
SHELF SUPPORT					W	M			I	D	FF			
WALL	B	C	(G)	P	W	M	T		(I)	D	FF			0.0
WINDOW SASH					W	(M)			I	D	(FF)			
WINDOW TRIM					W	(M)			I	D	(FF)			
WINDOW SILL <u>Tile</u>					W	M			I	D	FF			
FLOOR	(CP)				Vinyl	W			I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			

ROOM NAME Hall

_____ REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
	B	C	G	P	W	M	T	I	D	FF				
BASEBOARD					Vinyl	W	M		I	D	FF			
CEILING			(G)	P	W	M			(I)	D	FF			0.0
DOOR					(W)	M			(I)	D	FF			0.1
DOOR TRIM					(W)	M			(I)	D	FF			0.0
SHELF					(W)	M			I	D	(FF)			0.0
SHELF SUPPORT					(W)	M			I	D	(FF)			
WALL	B	C	(G)	P	W	M	T		(I)	D	FF			0.0
WINDOW SASH					W	M			I	D	FF			
WINDOW TRIM					W	M			I	D	FF			
WINDOW SILL					W	M			I	D	FF			
FLOOR	(CP)				Vinyl	W			I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			

ROOM NAME Bedroom 1

_____ REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
	B	C	G	P	W	M	T	I	D	FF				
BASEBOARD					Vinyl	(W)	M		(I)	D	FF			0.1
CEILING			(G)	P	W	M			I	D	FF			
DOOR					(W)	M			(I)	D	FF			0.0
DOOR TRIM					(W)	M			(I)	D	FF			0.1
SHELF					(W)	M			I	D	(FF)			0.0
SHELF SUPPORT					(W)	M			(I)	D	FF			0.0
WALL	B	C	(G)	P	W	M	T		(I)	D	FF			0.2
WINDOW SASH					W	(M)			I	D	(FF)			
WINDOW TRIM					W	(M)			I	D	(FF)			
WINDOW SILL <u>Tile</u>					W	M			I	D	FF			
FLOOR	(CP)				Vinyl	W			I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			
	B	C	G	P	W	M	T		I	D	FF			

ROOM NAME Bedroom 2 # _____ REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M		(D)	D	FF			0.0	
CEILING			(G)	P	W	M		(D)	D	FF			0.0	
DOOR					(W)	M		(D)	D	FF			0.0	
DOOR TRIM					(W)	M		(D)	D	FF			0.0	
SHELF					(W)	M		I	D	(FF)				
SHELF SUPPORT					(W)	M		(D)	D	FF			0.2	
WALL	B	C	(G)	P	W	M	T	(D)	D	FF			0.1	
WINDOW SASH					W	(M)		I	D	(FF)				
WINDOW TRIM					W	(M)		I	D	(FF)				
WINDOW SILL <u>Tile</u>					W	M		I	D	FF				
FLOOR	(CP)			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bedroom 3 # _____ REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M		(D)	D	FF			0.1	
CEILING			(G)	P	W	M		(D)	D	FF			0.0	
DOOR					(W)	M		(D)	D	FF			0.0	
DOOR TRIM					(W)	M		(D)	D	FF			0.2	
SHELF					(W)	M		(D)	D	(FF)				
SHELF SUPPORT					(W)	M		(D)	D	FF			0.3	
WALL	B	C	(G)	P	W	M	T	(D)	D	FF			0.0	
WINDOW SASH					W	(M)		I	D	(FF)				
WINDOW TRIM					W	(M)		I	D	(FF)				
WINDOW SILL <u>Tile</u>					W	M		I	D	FF				
FLOOR	(CP)			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bath # _____ REPORT # _____

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				(Vinyl)	W	M		I	D	FF				
CEILING			(G)	P	W	M		(D)	D	FF			0.1	
DOOR					(W)	M		(D)	D	FF			0.0	
DOOR TRIM					(W)	M		(D)	D	FF			0.1	
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		(D)	D	FF				
WALL	B	C	(G)	P	W	M	T	(D)	D	FF			0.0	
WINDOW SASH					W	(M)		I	D	FF				
WINDOW TRIM					W	(M)		I	D	FF				
WINDOW SILL <u>tile</u>					W	M		I	D	FF				
FLOOR	CP			(Vinyl)	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Kitchen

_____ REPORT # _____

COMPONENT	SUBSTRATE						PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M	I	D	FF				
CEILING			G	P	W	M	I	D	FF			0.1	
DOOR					W	M	I	D	FF			0.0	
DOOR TRIM					W	M	I	D	FF			0.0	
SHELF					W	M	I	D	FF				
SHELF SUPPORT					W	M	I	D	FF				
WALL	B	C	G	P	W	M	T	I	D	FF		0.2	
WINDOW SASH					W	M	I	D	FF			0.0	
WINDOW TRIM					W	M	I	D	FF			0.1	
WINDOW SILL <i>Tile</i>					W	M	I	D	FF				
FLOOR	CP			Vinyl	W		I	D	FF				
<i>Cupboard</i>	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			

ROOM NAME _____ # _____ REPORT # _____

COMPONENT	SUBSTRATE						PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M	I	D	FF				
CEILING			G	P	W	M	I	D	FF				
DOOR					W	M	I	D	FF				
DOOR TRIM					W	M	I	D	FF				
SHELF					W	M	I	D	FF				
SHELF SUPPORT					W	M	I	D	FF				
WALL	B	C	G	P	W	M	T	I	D	FF			
WINDOW SASH					W	M	I	D	FF				
WINDOW TRIM					W	M	I	D	FF				
WINDOW SILL					W	M	I	D	FF				
FLOOR	CP			Vinyl	W		I	D	FF				
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			

ROOM NAME _____ # _____ REPORT # _____

COMPONENT	SUBSTRATE						PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M	I	D	FF				
CEILING			G	P	W	M	I	D	FF				
DOOR					W	M	I	D	FF				
DOOR TRIM					W	M	I	D	FF				
SHELF					W	M	I	D	FF				
SHELF SUPPORT					W	M	I	D	FF				
WALL	B	C	G	P	W	M	T	I	D	FF			
WINDOW SASH					W	M	I	D	FF				
WINDOW TRIM					W	M	I	D	FF				
WINDOW SILL					W	M	I	D	FF				
FLOOR	CP			Vinyl	W		I	D	FF				
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			
	B	C	G	P	W	M	T	I	D	FF			