

# W. O., LTD.

(A DIVISION OF SCHAUER & ASSOCIATES, INC.)  
6960 S. 13th Street, P. O. Box 285  
Oak Creek, WI. 53154-0285  
(414)768-9588, (800)628-2590, Fax (414)764-2088

Report No. 4

## ON SITE LEAD PAINT X-RAY FLUORESCENCE EVALUATION RECORD

AGENCY Eric Metropolitan Housing Authority  
STREET 322 Warren Street UNIT/ADDRESS 610 Shelby  
CITY Sandusky, Ohio UNIT/LOCATION \_\_\_\_\_  
DATE 10-25-93

Substrate:

- B - Brick
- C - Concrete
- G - Gypsum
- Plaster
- Wood
- Metal
- T - Tile
- CP - Carpet

Paint Condition:

- intact
- D - defective (peeling, cracked, loose)
- factory finish

Comments:

---

---

---

---

---

---

---

---

---

---

This testing was accomplished utilizing:

A Warrington Microlead I, Revision 4, X-Ray Fluoroscope  
A Scitec Map 3 Spectrum Analyzer, X-Ray Fluoroscope


SIGNATURES

[Signature]

Technician/Inspector

Agency Representative


No indication of Lead Based Paint in this unit.  
 Paint samples taken for analysis  Lead indicated




UNIT ADDRESS 610 Shelby # \_\_\_\_\_ REPORT # \_\_\_\_\_

EXTERIOR LOCATIONS	SUBSTRATE					PAINT CONDITION			ALC	SEL	CLC	(NOTES)
	B	C	G	P	W	M	T	I				
SIDING	B	C			W	M		I	D			FF
EXTERIOR TRIM	B	C			W	M	T	I	D			FF
SOFFIT					W	M		I	D			FF
FACIA					W	M		I	D			FF
WINDOW EXTERIOR SASH					W	M		I	D			FF
WINDOW TRIM					W	M		I	D			FF
WINDOW PRIMARY SASH					W	M		I	D			FF
WINDOW SILL					W	M		I	D			FF
PORCH COLUMN		C			W	M		I	D			FF
PORCH CEILING					W	M		I	D			FF
PORCH FLOOR		C			W	M		I	D			FF
STAIR STEPS		C			W	M		I	D			FF
STAIR STRINGER					W			I	D			FF
DOOR					W	M		I	D			FF
DOOR TRIM					W	M		I	D			FF
DOOR JAMB					W	M		I	D			FF
SKIRTING	B	C	G	P	W	M	T	I	D			FF
THRESHOLD	B	C	G	P	W	M	T	I	D			FF
	B	C	G	P	W	M	T	I	D			FF
	B	C	G	P	W	M	T	I	D			FF
	B	C	G	P	W	M	T	I	D			FF
	B	C	G	P	W	M	T	I	D			FF

0.1  
0.0





ROOM NAME Bedroom 2 # \_\_\_\_\_ REPORT # \_\_\_\_\_

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD					Vinyl	(W)	M	I	D	(FF)				
CEILING				G	(P)	W	M	(I)	D	FF			0.2	
DOOR					(W)	M		I	D	(FF)				
DOOR TRIM					(W)	M		I	D	(FF)				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	(W)	M	T	I	D	(FF)				
WINDOW SASH					W	(M)		I	D	(FF)				
WINDOW TRIM					(W)	M		I	D	(FF)				
WINDOW SILL					(W)	M		I	D	(FF)				
FLOOR	(CP)				Vinyl	W		I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Hall # \_\_\_\_\_ REPORT # \_\_\_\_\_

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD					Vinyl	W	M	I	D	FF				
CEILING				G	(P)	W	M	(I)	D	FF			0.0	
DOOR					W	M		I	D	FF				
DOOR TRIM					W	M		I	D	FF				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	(W)	M	T	I	D	(FF)				
WINDOW SASH					W	M		I	D	FF				
WINDOW TRIM					W	M		I	D	FF				
WINDOW SILL					W	M		I	D	FF				
FLOOR	(CP)				Vinyl	W		I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bath # \_\_\_\_\_ REPORT # \_\_\_\_\_

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD					Vinyl	W	M	I	D	FF				
CEILING <u>Vinyl</u>				G	P	W	M	I	D	FF				
DOOR					(W)	M		I	D	(FF)				
DOOR TRIM					(W)	M		I	D	(FF)				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL <u>Vinyl</u>	B	C	G	P	W	M	T	I	D	FF				
WINDOW SASH					W	(M)		I	D	(FF)				
WINDOW TRIM					(W)	M		I	D	(FF)				
WINDOW SILL					(W)	M		I	D	(FF)				
FLOOR	CP				(Vinyl)	W		I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Kitchen

#

REPORT #

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M	I	D	(FF)					
CEILING			G	(P)	W	M	(I)	D	FF				0.1	
DOOR					W	(M)	I	D	(FF)					
DOOR TRIM					(W)	M	I	D	(FF)					
SHELF					W	M	I	D	FF					
SHELF SUPPORT					W	M	I	D	FF					
WALL	B	C	G	P	(W)	M	T	I	D	(FF)				
WINDOW SASH					W	(M)	I	D	(FF)					
WINDOW TRIM					(W)	M	I	D	(FF)					
WINDOW SILL					(W)	M	I	D	(FF)					
FLOOR	CP			(Vinyl)	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bedroom 3

#

REPORT #

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M	(I)	D	FF				0.2	
CEILING			G	(P)	W	M	(I)	D	FF				0.1	
DOOR					(W)	M	I	D	(FF)					
DOOR TRIM					(W)	M	(I)	D	FF				0.2	
SHELF					W	M	I	D	FF					
SHELF SUPPORT					W	M	I	D	FF					
WALL	B	C	G	(P)	W	M	T	(I)	D	FF			0.1	
WINDOW SASH					W	(M)	I	D	(FF)					
WINDOW TRIM					(W)	M	(I)	D	FF				0.0	
WINDOW SILL					(W)	M	(I)	D	FF				0.1	
FLOOR	(CP)			(Vinyl)	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bedroom 4

#

REPORT #

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M	(I)	D	FF				0.1	
CEILING			G	(P)	W	M	(I)	D	FF				0.0	
DOOR					(W)	M	I	D	(FF)					
DOOR TRIM					(W)	M	(I)	D	FF				0.3	
SHELF					(W)	M	(I)	D	FF				0.1	
SHELF SUPPORT					(W)	M	(I)	D	FF				0.0	
WALL	B	C	G	(P)	W	M	T	(I)	D	FF			0.2	
WINDOW SASH					W	(M)	I	D	(FF)				0.4	
WINDOW TRIM					(W)	M	(I)	D	FF				0.0	
WINDOW SILL					(W)	M	(I)	D	FF				0.0	
FLOOR	(CP)			(Vinyl)	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME Bedroom 5

# \_\_\_\_\_

REPORT # \_\_\_\_\_

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	(W)	M		(1)	D	FF			0.1	
CEILING			G	(P)	W	M		(1)	D	FF			0.0	
DOOR					(W)	M		I	D	FF				
DOOR TRIM					(W)	M		(1)	D	FF			0.2	
SHELF					(W)	M		(1)	D	FF				
SHELF SUPPORT					(W)	M		I	D	FF				
WALL	B	C	G	(P)	W	M	T	(1)	D	FF			0.0	
WINDOW SASH					W	(M)		I	D	FF				
WINDOW TRIM					(W)	M		(1)	D	FF			0.1	
WINDOW SILL					(W)	M		(1)	D	FF			0.0	
FLOOR	(CP)			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME \_\_\_\_\_

# \_\_\_\_\_

REPORT # \_\_\_\_\_

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M		I	D	FF				
CEILING			G	P	W	M		I	D	FF				
DOOR					W	M		I	D	FF				
DOOR TRIM					W	M		I	D	FF				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	W	M	T	I	D	FF				
WINDOW SASH					W	M		I	D	FF				
WINDOW TRIM					W	M		I	D	FF				
WINDOW SILL					W	M		I	D	FF				
FLOOR	CP			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				

ROOM NAME \_\_\_\_\_

# \_\_\_\_\_

REPORT # \_\_\_\_\_

COMPONENT	SUBSTRATE							PAINT CONDITION			ALC	SEL	CLC	(NOTES)
BASEBOARD				Vinyl	W	M		I	D	FF				
CEILING			G	P	W	M		I	D	FF				
DOOR					W	M		I	D	FF				
DOOR TRIM					W	M		I	D	FF				
SHELF					W	M		I	D	FF				
SHELF SUPPORT					W	M		I	D	FF				
WALL	B	C	G	P	W	M	T	I	D	FF				
WINDOW SASH					W	M		I	D	FF				
WINDOW TRIM					W	M		I	D	FF				
WINDOW SILL					W	M		I	D	FF				
FLOOR	CP			Vinyl	W			I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				
	B	C	G	P	W	M	T	I	D	FF				