ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Living Room												
Walls	Paneling											Negative
CE	0	0	0	0								Negative
D	.5	.6	.7	.60	.5	.5	.5	.50	.10			Negative
EDC	Covered Aluminum											Negative
IDC	No Paint											Negative
DJ	6.9	7.1	6.4	6.8								Abate
WC	0	0	0	0								Negative
Mantel	0	0	0	0								Negative
Dining Room												
W	Paneled											Negative
CE	0	0	0	0								Negative
Archway - IDC	0	0	0	0								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Archway - EDC	0	0	0	0								Negative
Archway - DJ	0	0	0	0								Negative
WC	0	0	0	0								Negative
Kitchen												
W	.1	.1	.1	.10								Negative
CE	.3	.1	.1	.16								Negative
Wood Siding	0	0	0	0								Negative
Archway - EDC	0	0	0	0								Negative
Archway - IDC	0	0	0	0								Negative
Archway - DJ	0	0	0	0								Negative
WC	.1	.1	0	.06								Negative
WS	.3	.2	.3	.26								Negative
WA	.3	.1	.1	.16								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Cabinet Sides	.1	.1	.1	.10								Negative
Cabinet Door	.2	.1	0	.10								Negative
Door	.2	.2	.1	.16								Negative
EDC	.3	.1	.1	.16								Negative
IDC	.3	.3	.3	.30								Negative
DJ	.1	.1	.1	.10								Negative
Restroom												
W	.4	.4	.4	.40								Negative
CE	.2	.1	.1	.13								Negative
Wood Siding	.3	.3	.1	.23								Negative
D	.2	.2	.2	.20								Negative
EDC	.3	.1	.1	.16								Negative
IDC	.2	0	0	.06								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
DJ	.1	0	0	.03								Negative
WS	.1	.2	.3	.20								Negative
WC	.2	.2	.2	.20								Negative
WA	.1	.1	0	.06								Negative
D 2	.4	.4	.4	.40								Negative
EDC	.4	.4	.4	.40								Negative
IDC	.3	.2	.2	.23								Negative
DJ	.3	.1	.1	.16								Negative
Bedroom #1												
Wall	.1	.1	.1	.10								Negative
Ceiling	.1	.2	.1	.13								Negative
BB	.2	.2	0	.13								Negative
WC	.1	.3	.1	.16								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
WS	.2	.2	.1	.16								Negative
WA	0	0	0	0								Negative
D	.2	.1	.1	.13								Negative
EDC	.1	.4	.1	.20								Negative
IDC	.2	.2	.2	.20								Negative
DJ	.1	.1	0	.06								Negative
Bdrm #1 Closet												
W	.2	.1	.1	.13								Negative
CE	.1	.1	0	.06								Negative
BB	.2	.1	0	.10								Negative
Coat Rack	3.1	3.9	3.7	3.56								Abate
WA	0	0	0	0								Negative
EDC	0	0	0	0								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
IDC	0	0	0	0								Negative
DJ	0	0	0	0								Negative
Stairway												
Walls	Paneled											Negative
CE	0	0	0	0								Negative
D	.2	.1	.1	.13								Negative
EDC	.1	.1	.1	.10								Negative
DJ	.2	.1	.1	.13								Negative
IDC	0	0	0	0								Negative
Hand Rail	0	0	0	0								Negative
Stairs	Carpet											Negative
Stair Stringer	.2	.1	.1	.13								Negative
Stair Rail	.1	.1	.1	.10								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Stair Post	.2	.4	.4	.33								Negative
Baseboard	.2	.4	.1	.23								Negative
CM	.2	.2	0	.13								Negative
WC	.2	.2	.1	.16								Negative
Bedroom #1												
Walls	0	0	0	0								Negative
CE	0	0	0	0								Negative
BB	0	0	0	0								Negative
D	.1	.1	0	.06								Negative
EDC	.2	.1	.1	.13								Negative
IDC	.2	.2	0	.13								Negative
DJ	.2	.1	.3	.20								Negative
Floor	.1	.1	.1	.10								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Bedroom #2												
W	.2	.1	.1	.13								Negative
CE	.2	.1	0	.10								Negative
D	.2	.1	.1	.13								Negative
EDC	0	0	0	0								Negative
IDC	0	0	0	0								Negative
DJ	0	0	0	0								Negative
BB	0	0	0	0								Negative
WC	0	0	0	0								Negative
Bedroom #3												
W	0	0	0	0								Negative
CE	0	0	0	0								Negative
BB	0	0	0	0								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
D	.2	.1	.1	.13								Negative
EDC	.1	.1	0	.06								Negative
IDC	.1	.4	.1	.20								Negative
DJ	.2	.1	.1	.13								Negative
WC	.2	.2	.2	.20								Negative
Bdrm #3 Closet												
W	.1	.1	.1	.10								Negative
CE	0	0	0	0								Negative
EDC	.2	.1	0	.10								Negative
IDC	.2	.1	.1	.13								Negative
DJ	.1	.1	.1	.10								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Bedroom #4												
W	Paneled											Negative
CE	0	0	0	0								Negative
WC	0	0	0	0								Negative
CM	.2	.1	.1	.13								Negative
D	.1	.2	0	.10								Negative
EDC	.2	.1	.1	.13								Negative
IDC	.1	.1	0	.06								Negative
DJ	0	0	0	0								Negative
Closet/Right	.1	.2	0	.10								Negative
W	0	0	0	0								Negative
CE	0	0	0	0								Negative
CM	.2	.2	.2	.20								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Bedroom #4												
W	Paneled											Negative
CE	0	0	0	0								Negative
WC	0	0	0	0								Negative
CM	.2	.1	.1	.13								Negative
D	.1	.2	0	.10								Negative
EDC	.2	.1	.1	.13								Negative
IDC	.1	.1	0	.06								Negative
DJ	0	0	0	0								Negative
Closet/Right	.1	.2	0	.10								Negative
W	0	0	0	0								Negative
CE	0	0	0	0								Negative
CM	.2	.2	.2	.20								Negative

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Closet/Left	.2	.1	.1	.13								Negative
W	.2	.2	0	.13								Negative
CE	.2	.2	.2	.20								Negative
CM	.2	.1	.1	.13								Negative
Basement												
W	0	0	0	0								Negative
CE	0	0	0	0								Negative
D	.1	0	0	.03								Negative
EDC	.1	.1	0	.06								Negative
IDC	.2	.2	.2	.20								Negative
DJ	.2	0	0	.06								Negative
Wood Siding/Gr	.1	.1	0	.06								Negative
Stair Header	6.6	6.9	7.1	6.86								Abate

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Stair Riser	.2	.1	.1	.13								Negative
MD	.6	.7	.6	.63	.5	.5	.5	.50	.13			Negative
EDC	Aluminum Cover											Negative
IDC	0	0	0	0								Negative
DJ	7.8	7.9	8.4	8.03								Abate
Corner Edge	0	0	0	0								Negative
Coat Rack	10.0	10.0	10.0	10.0								Abate
White/Siding	9.3	9.7	9.6	9.53								Abate
White/Door	9.3	9.4	9.1	9.26								Abate
White/EDC	9.2	9.1	9.0	9.10								Abate
White/IDC	8.9	9.1	9.3	9.10								Abate

ENVIRONMENTAL CONTROL TECHNOLOGIES
LBP XK-3 SAMPLE SHEET

Date/Time: March11, 1993 Apartment # 1323 Stone Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm2)				S.E.L. (mg/cm2)				C.L.C. (mg/cm2)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Exterior												
Porch	.2	.3	.1	.20								Negative
Porch Rail	.1	.1	.1	.10								Negative
Metal Rail	1.0	1.0	1.0	1.0	.7	.8	.7	.73	.27			Negative
Porch Posts	10.0	10.0	10.0	10.0								Abate
Porch Header	10.0	10.0	10.0	10.0								Abate
Porch Ceiling	.4	.4	.4	.40								Negative
Soffitt	10.0	10.0	10.0	10.0								Abate
Fascia	10.0	10.0	10.0	10.0								Abate