

ENVIRONMENTAL CONTROL TECHNOLOGIES

LBP XK-3 SAMPLE SHEET

Date/Time: February 16, 1993 Apartment # 711 Sycamore Project: Area 8 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm ²)				S.E.L. (mg/cm ²)				C.L.C. (mg/cm ²)	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
Stair Rail	.3	.3	.3	.3								Negative
Wide Baseboard	3.3	3.5	3.4	3.4								Abate
Pipe Chase	.3	.2	.2	.23								Negative
Narrow Baseboard	0	0	0	0								Negative
<u>Closet (Attic)</u>												
Door	10.0	10.0	10.0	10.0								Abate
Door Jamb	10.0	10.0	10.0	10.0								Abate
Shelf	2.8	2.8	2.9	2.83								Abate
Shelf Bracket	2.8	2.7	2.6	2.7								Abate
Wall	2.3	2.7	2.5	2.5								Abate
Ceiling	.3	.5	.3	.36								Negative
RR (Attic)/EDC	0	0	0	0								Negative
DJ	0	0	0	0								Negative

IDC 0 0 0 0

Negative

