





ENVIRONMENTAL CONTROL TECHNOLOGIES  
LBP XK-3 SAMPLE SHEET

Date/Time: February 18, 1993 Apartment # 1109 Wamajo St. Project: Area 7 Site: Erie Metro. H.A.

Sample Number	Reading (mg/cm <sup>2</sup> )				S.E.L. (mg/cm <sup>2</sup> )				C.L.C. (mg/cm <sup>2</sup> )	Conformation Test		Result Neg./Abate
	1	2	3	Avg	1	2	3	Avg		No.	Result	
BR 1/CW	0	0	0	0								Negative
BR 2/W	0	0	0	0								Negative
BR 2/CW	0	0	0	0								Negative
BR 3/W	0	0	0	0								Negative
BR 3/CW	0	0	0	0								Negative
BR 4/W	0	0	0	0								Negative
BR 4/CW	0	0	0	0								Negative
Ext. WC/Red	1.5	1.6	1.5	1.53						1109-01		Abate
Ext. WC/White	0	.1	0	.033								Negative

Red Paint is located on the exterior window casings and exterior windows/5 in all.